



975 85th Avenue SE ▪ Olympia, WA 98501 ▪ Phone 360-273-7604 ▪ www.mechspecialties.com

SERVICE BULLETIN LOAD BEAM IMPROVEMENT

SERVICE BULLETIN NO.: MS-909-SB-2

DATE: July 19, 2019

ATTENTION: OWNERS / OPERATORS OF MECHANICAL SPECIALTIES, LLC MODEL 909
CARGO HOOK FOR THE SIKORSKY UH-60 HELICOPTER

STC NO.: SR02617SE

SUBJECT: ACCELERATED WEAR ON 9104-1 LOAD BEAM

APPLICABILITY: HOOK SERIAL NOs. 1001-1019

COMPLIANCE: OPTIONAL

DESCRIPTION:

Occurrences of accelerated wear on the 9104-1 Load Beam (MSI-MNL020 Overhaul Manual, Item 4A) have been reported. To address these concerns, Mechanical Specialties is offering the replacement 9104-2 Load Beam made from more wear resistant steel, featuring an improved load seat.

ACCOMPLISHMENT INSTRUCTIONS:

This limited warranty replacement offer is valid for 12 months from the date of original purchase of each cargo hook assembly. This service includes a normal overhaul at no charge. Any requests for load beam replacement beyond 12 months of the original purchase date will be subject to standard parts and labors charges.

If the end of the 12 month warranty period conflicts with your operating season, please contact sales@mechspecialties.com prior to the end of the warranty period for an extension request.

Please return the Cargo Hook assembly to Mechanical Specialties:

Mechanical Specialties, LLC
975 85th Ave SE,
Olympia, WA 98501

To ensure availability of parts, please call or email to schedule your overhaul today. Turnaround time is expected to be 3-5 business days.

If you have questions or concerns, please do not hesitate to contact Mechanical Specialties, LLC at (360) 273-7604.